



EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com> / bostonlab@emsl.com

EMSL Order: 131901531
Customer ID: UEC63
Customer PO:
Project ID:

Attention: Ammar Dieb Universal Environmental Consultants 12 Brewster Road Framingham, MA 01702 Project: 219080.00 / Maynard Green Meadow School / Pre K/ K Wing	Phone: (508) 628-5486 Fax: (508) 628-5488 Received Date: 03/06/2019 18:15 PM Analysis Date: 03/06/2019 Collected Date: 03/06/2019
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Test Report: Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Appendix A to Subpart E

Sample	Location	Volume (Liters)	Area Analyzed (mm ²)	Non Asb	Asbestos Type(s)	#Structures		Analytical Sensitivity (S/cc)	Asbestos Concentration	
						≥0.5μ < 5μ	≥5μ		(S/mm ²)	(S/cc)
1 131901531-0001	Inside- Room 7L	1245.00	0.0645	0	None Detected	0	0	0.0048	<16.00	<0.0048
2 131901531-0002	Inside- Room 7J	1235.00	0.0645	0	None Detected	0	0	0.0048	<16.00	<0.0048
3 131901531-0003	Inside Hallway	1245.00	0.0645	0	None Detected	0	0	0.0048	<16.00	<0.0048
4 131901531-0004	Inside Room 7F	1245.00	0.0645	0	None Detected	0	0	0.0048	<16.00	<0.0048
5 131901531-0005	Inside Room 7E	1235.00	0.0645	0	None Detected	0	0	0.0048	<16.00	<0.0048
6 131901531-0006	Outside Containment	1254.00			Not Analyzed					N/A
7 131901531-0007	Outside Containment	1254.00			Not Analyzed					N/A
8 131901531-0008	Outside Containment	1245.00			Not Analyzed					N/A
9 131901531-0009	Outside Containment	1254.00			Not Analyzed					N/A
10 131901531-0010	Outside Containment	1254.00			Not Analyzed					N/A
11 131901531-0011	Inside Blank	0.00			Not Analyzed					N/A
12 131901531-0012	Outside Blank	0.00			Not Analyzed					N/A
13 131901531-0013	Field Blank	0.00			Not Analyzed					N/A

Analyst(s)

Steve Grise (5)

Steve Grise, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. Results reported in both structures/cm3 and structures/mm2 are dependent on the volume of air sampled and measured by non-laboratory personnel are not the responsibility of EMSL and are not covered by the laboratory's NVLAP accreditation. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-139 and VT AL998919

Initial report from: 03/06/2019 19:53 PM